

Service visit report

Lighting inspection · Riverside Recreation Centre

Reference: SV-026-014

Date: 4 September 2026

Technician: Jordan Lee

Visit summary

The centre reported that the entrance lights switched off before the last evening class finished. We inspected the lighting circuit, checked the control panel and tested the timer against the centre's opening hours. All light fittings were working correctly.

Work completed

We replaced a faulty timer relay and updated the weekday schedule so the entrance stays lit until 10:30 pm. The lights passed three switching tests, and reception staff checked the manual override. The service charge of £185 covers the replacement relay and labour.

Next steps

- Check the timer after the next power outage.
- Record any flickering or delayed switch-on.
- Book the routine inspection for December 2026.

Status: Completed. No return visit is needed.